# Radon Testing Results -SCESD
# Action Level is 4.0 pCi/L

| Site Name | Building Name | Room Description (per floor plan) | Kit serial # | Date sampled | Type of test | Results (pCi/L) |
|---|---|---|---|---|---|---|
| SCESD - Gold Beach Office | Gold Beach office | Audiology - testing area | AE833064 | 9/9/2020 | Blank | 1.2 |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |